## EPA REGION VI

SUK

May 28, 1985

ISSS JUN -6 AM II: 20 SUPERFUND BRANCH

Sun Refining and Marketing Company P O Box 2039 Tulsa OK 74102

Mr. Gary Guerra U. S. Environmental Protection Agency Superfund Compliance (6AW-SC), Region VI 1201 Elm St. Dallas, TX 75270 Sun Refinery+ MarketingCo.

Filedin SAVOI#2

Dear Mr. Guerra:

Please refer to Mr. Allyn M. Davie's letter dated May 6, 1985 concerning an inactive landfill site which was located at the Sun Refinery in Tulsa, Oklahoma.

Attached is a copy of a letter and accompanying map made up for me by the engineer (now retired) who followed the cleanup of the subject landfill. Also attached are copies of photos taken during the testing to determine the location and materials contained in the landfill. No photos are available of the cleanup or the site now. I understand the EPA contractor took photos during their visit in 1934 which should be available to you.

As you can see from Mr. Callahan's letter, the material was recovered and made into roadbed material for use within the refinery.

The wells located in the former area of the landfill are associated with our oil recovery project and are only used for monitoring presence of oil on water table and groundwater table levels. The only wells which we monitor groundwater constituents are located approximately 2600 feet up gradiant from the site of the subject landfill site and, therefore, would provide no usable data.

Please contact me at 918-586-7374 or Mrs. Sidney Cabbiness at 918-586-7574 if we can be of any further service.

Sincerely,

William K. Clark

William R. Clarke, P.E. Chief Environmental Engineer

WRC:dl attachments

SUPERFUND FILE

AUG 27 1992

REORGANIZED